

Hunters Point RU-C2 Remedial Action

Building 251 1-Month Post Injection Sampling Results

Well ID		RUC2MW6B	RUC2MW7A	RUC2MW13A	RUC2MW13B	RUC2MW14A
Sample ID	PAL	RUC2MW6B-1	RUC2MW7A-1	RUC2MW13A-1	RUC2MW13B-1	RUC2MW14A-1
Sample Date		8/20/13	8/21/13	8/23/13	8/23/13	8/21/13
Volatile Organic Compounds						
1,2,4-Trimethylbenzene	25	0.5U	0.5U	2.5U	0.5U	0.5U
1,2-Dichlorobenzene	2600	0.5U	0.3J	4.7	0.5U	0.5U
1,2-Dichloropropane	1.1	0.5U	0.5U	2.5U	0.5U	0.5U
1,4-Dichlorobenzene	2.1	0.5U	7.5	120	0.5U	0.5U
Benzene	0.5	0.5U	0.4J	3.4	0.5U	0.5U
Carbon Tetrachloride	0.5	2.3	0.5U	2.5U	19	0.5U
Chlorobenzene	390	0.5U	36	670	0.5U	0.5U
Chloroform	0.7	1.5	0.5U	0.9J	13	0.5U
cis-1,2-Dichloroethene	210	0.5U	0.2J	14	0.5U	0.5U
Isopropylbenzene	7.8	0.5U	0.5U	2.5U	0.5U	0.5U
Methylene Chloride	27	10U	10U	50U	0.2J	10U
Tetrachloroethene	0.5	0.5U	0.6	3.1	0.5U	0.5U
trans-1,2-Dichloroethene	180	0.5U	0.5U	2.5U	0.5U	0.5U
Trichloroethene	2.9	0.5U	0.4J	1.8J	0.5U	0.5U
Trichlorofluoromethane	180	4.1	1U	5U	0.2J	1U
Vinyl Chloride	0.5	0.5U	0.5U	3.2	0.5U	0.5U

*Not Validated